

Cause of electrical box explosion in Guyana

Preview

"Massy Gas Products Guyana Ltd. has confirmed that a faulty, non-recommended regulator was the cause of a flash explosion that injured two individuals early this morning, Thursday, September 4, 2025, at a residence in 'C' Field Sophia. has confirmed that. GEORGETOWN, Guyana -- President Irfaan Ali has ordered a full-scale investigation into Sunday evening's explosion at the Mobil Service Station at the corner of Regent and King Streets, Georgetown, which claimed the life of a six-year-old girl and left two other children critically injured. Concerns have been raised about the Massy Gas cylinder used, but the company, in a release, blamed the explosion on a "non-recommended" regulator.

See below the full release from Massy Gas Products: Massy Gas Products Guyana Ltd. has confirmed that a faulty,

"Massy Gas Products Guyana Ltd. has confirmed that a faulty, non-recommended regulator was the cause of a flash explosion that

While on official duty in the Kingdom of Saudi Arabia, President Dr Mohamed Irfaan Ali has ordered a comprehensive

The Georgetown Chamber of Commerce and Industry (GCCI) has noted revelations that the explosion at the Mobil

A fuse box explosion is suspected to be the cause of the La Parfaite Harmonie fire that

Government agencies examining a number of fires and explosions connected to gas cylinders are to do further

Substation explosion causes power outage, transformer failure, and grid damage. Learn risks, fire suppression system design, and

Carelessness on top The most common cause of Arc Flash and other electrical accidents is carelessness. No matter

AI enhanced image released by the Guyana Police Force of the wanted suspect in the deadly gas station explosion

Full release issued by the Guyana Police Force: The Guyana Police Force wishes to provide an update on the

Cause of electrical box explosion in Guyana

The Guyana Police Force this morning issued an updated wanted bulletin for the suspect believed to have planted an

See below full statement issued by the Guyana Fire Service: The Guyana Fire Service is actively investigating an explosion that

An eight-year-old child is now dead and two others injured along with two adults, following

See full release from the Office of President Dr Irfaan Ali, issued on Monday October 27, 2025: While on official duty

The Guyana Fire Service is actively investigating an explosion that caused extensive damage, authorities confirmed.

Electrical explosion events produce arc blast, pressure waves, shrapnel, fire, and toxic smoke causing severe injuries and equipment

Web: <https://www.millstraining.co.za>

